




PORT OPERATIONS

Local Notice to Mariners 22/17

West Buoy & Two Pellet Buoys Removed From Outer Harbour

Mariners are advised that the West buoy and two Pellet buoys previously marking the southern edge of the Recreation Area have been removed from the Outer Harbour, in order to make way for the new DWDR exclusion zone buoyage. This now leaves buoyage in this area in line with the latest edition of chart BA1698 (extract below).



Paul Brown
Harbour Master

04th April 2017

Notices Remaining In Force:

- 07/15 – ED3 Extension Side Fender Temp Removal (amended)
- 70/15 – Pier Alpha Nav Lt reinstated. HIL and Fog Signal Unserviceable (updated)
- 40/16 – Decommissioned Mooring Equipment

46/16 – Granville Dock Marina depths
55/16 – Admiralty Pier HIL
07/17 – North East Buoy Off Station
09/17 – Survey Work Spoil Ground
16/17 – Diving Operations – Prince of Wales Pier
17/17 – Installation of DWDR Exclusion Zone
18/17 – Dunkirk Jetty Light
19/17 – Kreeft survey and seabed investigation work
20/17 - Demolition Works – Dunkirk Jetty
21/17 - Dredging & Scour Removal/Pile Cutting – Old Hoverport & Approaches
22/17 - West Buoy & Two Pellet Buoys Removed From Outer Harbour