



PORT OPERATIONS

Local Notice to Mariners 24/17

NE Buoy Light Unreliable

Mariners are advised that the NE Buoy (located to the West of ferry berth ED9) is currently displaying an irregular light.

The correct light (Fl.4.Y.6s) will be restored as soon as practicable.

Paul Brown
Harbour Master

20th April 2017

Notices Remaining In Force:

- 70/15 – Pier Alpha Nav Lt reinstated. HIL and Fog Signal Unserviceable (updated)
- 40/16 – Decommissioned Mooring Equipment
- 46/16 – Granville Dock Marina depths
- 55/16 – Admiralty Pier HIL
- 17/17 – Installation of DWDR Exclusion Zone
- 18/17 – Dunkirk Jetty Light
- 20/17 - Demolition Works – Dunkirk Jetty
- 21/17 - Dredging & Scour Removal/Pile Cutting – Old Hoverport & Approaches
- 22/17 - West Buoy & Two Pellet Buoys Removed From Outer Harbour
- 23/17 – Diving Operations Old Seacat Berth Inner Harbour
- 24/17 – NE Buoy Light Unreliable