



PORT OPERATIONS

Notice to Mariners 70/15

Pier Alpha

Navigation Lights, HIL & Fog Signal Unserviceable

Mariners are advised that the Navigation Lights (Q.R), High Intensity Light (Q.R occas) and Fog Signal (Siren (2) 10s (occas) located on the end of Pier Alpha are unserviceable.

Work to restore use is being progressed as soon as possible.

Paul Brown
Harbour Master

6th December 2015

Notices Remaining In Force:

24/12 - Pier E Dolphin
34/12 - Western Entrance Jetstream
43/13 - Tug use when berthing ED2
01/14 - Fender Damage Pier B
05/14 - Pier A Extension Fenders
07/14 - Southern Breakwater - Closure
09/14 - ED3 Side Fenders
47/14 - ED9 Berth Missing Side Fender
48/14 - ED8/9 Stern Fender damage
49/14 - Beacon No.7 removal
1/15 - Tide Tails - Harbour Buoys
2/15 - Breastlines ED8
7/15 - ED3 Extension Side Fender Temp Removal (amended)
15/15 - ED6 Stern Fender damage
54/15 - Coralwater Tidal Restriction
63/15 - General Directions 2015 Consultation
69/15 - Geotechnical Seabed Survey
70/15 - Pier Alpha Nav Lts, HIL and Fog Signal Unserviceable